



OEM Design Definition Issues

**NAVAIR public release SPR-2014-342
Distribution A -- Approved for public release
distribution is unlimited**

**ISSC Engineering Team, FRCSW
Presented 28 April 2014**

**Code 43353
Rick Mendoza**




Synopsis

- Existing Manufacturing Process Requires 3D Solid Model for CAM Software.
 - 2D, Blueprint Defined Engineering Data
 - 2D-3D translation subject to Human error.
 - OEM Blueprint can incorrectly define Part.
 - MBD Data
 - Can have quality issues
 - Can incorrectly define part




Misinterpretation of the Blueprint




3D Model of Structural
Former – Translated from
2D Blueprint



Misinterpretation of the Blueprints




View Looking FWD




View Looking AFT



Misinterpretation of the Blueprints



Blueprint Errors – Missing information




Structural Former




Blueprint Errors – Missing information

Nacelle
Moldline


Duct
Moldline



Blueprint Errors – Missing information




Blueprint Errors – Wrong Information



Fin Dent ML (Correct)


Missile Fairing ML



Example of incorrect call-out on a blueprint




Blueprint Errors – Wrong Information




Blueprint Errors – Wrong Information

Discovered after Aircraft Fuselage already spliced together
 Protrusion of Former prevented MLG Door from closing
 Required Cut and Splice repair after former installation



Former Cut Area





Repair Piece with Correct Mold Line




Blueprint Errors – Wrong Information

Complete Splice Repair Installation



Blueprint Errors – Conflicting information




Hinge Half Assembly



Blueprint Errors – Conflicting information

WING REF PLANE


WING LWR OML



Blueprint Errors – Conflicting information

WING REF PLANE


WING LWR OML




Reproduction of Section View F-F After Correction




Part Received from DLA Supply



MBD Quality Issues




26 3D UNIGRAPHICS MODEL IS MASTER DEFINITION OF THIS PART




Vs.



MBD Quality Issues



MBD Quality Issues




OEM MBD Detail

This cannot be Manufactured without a CNC Programmer adjusting the tool-path.




MBD Quality Issues




Manufacturing Model Management System (3MS)

Check 1: Ensure Model is True to Blueprint



Original blueprint




Created from Model Interrogation



Manufacturing Model Management System (3MS)

Check 2: Scan Aircraft Sample and Compare to Model




	Neg	Nom	Pos	Total	Pct
In Tolerance:	6354	70	6834	13258	41.86
Out of Tolerance:	8258		10154	18412	58.14
Failed Points:					
Total Points:	14612	70	16988	31670	100.00

	DX	DY	DZ	3D
Maximum Deviation:	0.2080	0.1840	0.3230	0.1050
Minimum Deviation:	-0.0900	-0.0870	-0.2790	-0.4120
Deviation Range:	0.2980	0.2710	0.6020	0.5170
Average Deviation:	0.0000	0.0000	0.0000	0.0050
RMS Deviation:	0.0080	0.0090	0.0240	0.0270
Standard Deviation:	0.0080	0.0090	0.0240	0.0260



3MS





FRC SW 2D-3D Translation Control Documents
FRC SW INST 4790.4
FRC SW INST 13600.2

Questions?

ISSC Engineering Team, FRC SW
Presented 28 April 2014

Code 43353
Rick Mendoza

